





HIETAKARI®




8/25 6IRLM

S48




# Parts




1. x2



2. x4




3. x5



4/83 31RLM



4/83 14RLM




6. x2



7. x1




8. x1




9. x2

8/65 242LM




10. x1



11. x2




12. x1




13. x2

4/83 99RLM



14. x2

# Tools



A

$\varnothing 4$  mm

$\varnothing 5$  mm


B

C – Silicone


D – Glue




E






F








G







1






2

 $\varnothing 4\text{ mm}$ 



3



4



5



6

