





HIETAKARI®




8/25 6JRLM

S49




Parts




1. x4



2. x4




3. x6



4/83 31RLM



4/83 14RLM




6. x1




7. x1



8. x1




8/85 51RLM




10. x4

4/83 99RLM




11. x1



12. x1

Tools




A

$\varnothing 4$ mm
 $\varnothing 5$ mm
B


C – Silicone
D – Glue




E







F







G




1





2

 $\varnothing 4\text{ mm}$ 



5



3



D



3

4

