





HIETAKARI®




8/25 6QRLM

S57




Parts




1. x1



2. x1




3. x2



4/83 31RLM




4/83 14RLM




6. x1



7. x1




8. x2




4/83 99RLM


9. x2






10. x2

Tools







1





2




$\varnothing 4\text{ mm}$








3




5




3



4



10



8

