





HIETAKARI®


CE

8/25 6LRLM

S52




Parts




1. x1



2. x1




3. x2




4/83 31RLM




4/83 14RLM



6. x1




7. x1




8. x2

8/65 242LM




4/83 99RLM

9. x2



10. x2

Tools



A

$\varnothing 4$ mm


$\varnothing 5$ mm

B


C – Silicone




E






F








G








1





2



3



4



8

